

Lake Vue Electric, Inc.
9322 Greenback Lane, SP E
PO Box 655
Orangevale, CA 95662

Estimate

Date	Estimate No.
2/21/2022	2182

Name/Address

Sue Ann Sathre
5681 River Oak Way
Carmichael, CA 95608

Ship To

Home Electrical Inspection
4333 Mulford Ave
Carmichael

Customer E-mail

sueannsathre@aol.com

Project

4333 Mulford Ave.

Description

We propose to furnish material and labor at the above address per our conversation with Sue Ann. Wiring and installations to include the following:

Main electrical is 100 amp overhead Zinsco panel Breakers were removed to inspect bussing for pitted and burn marks and none were found. This panel is in good shape and is not an issue at this time.

This house was built when a 2-wire system was installed in bedrooms and front rooms. Some 3-wire outlets were installed where no ground is present giving a look of a grounded outlet where there is not. Suggest grounding outlets or change back to 2-wire outlets.

GFI outlets did not trip when tested in kitchen. Recommend check by electrician.

Material and labor to ground outlet: \$195.00 per outlet

Material and labor to replace defective GFI: \$140.00 per GFI

CA Lic. #398381

Total

\$0.00

Phone #

9169880271

E-mail

LAKVUELECT@SBCGLOBAL.NET